

BUILDING SEFTY CERTIFICATE

No.101...

Date : 02/03/2020

The
Satpuda Valley Public School
Sahutola, Manjhapur, Garra, Balaghat ✓

The School Building has been inspected and structure seems usable for the purpose of school. However the buildings during construction has not been supervised by this office so the school, management should have arrangements for the natural calamities i.e. sudden fallure of stone pattles, earthquakes, fire, flood etc.

The certificates is valid for the session.....(2019-20..)

Only

(Signature)
S/ED
20/02/2020

(Signature)
Assistant Engineer
Sub Divisional Office
P.W.D. Sub Dn.No.?
P.W.D. Sub Dn.No.?
Balaghat